


Marvell 9128 Firmware update to SP1807


Note: If your Motherboard have Marvell SATA controller please disable it first.

How to update.

1. Please unzip SP1807.zip
2. Please run the firmware update on DOS
3. Please copy SP1807 folder to C:\
4. Key in P.bat then Enter



5. Firmware will start to update when finish will shown Flashed Successful!!



How to check

1. Please connect SATA HDD to 9128 HBA any port.
2. Please use Ctrl+M into 9128 BIOS.
3. The SP1807 BIOS version and Firmware version will shown on screen

